

010605-010614.02H

4E

Subject to

7-DEC1961

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME SAN ROCCO REPORT heghom No. 1742

MBS due 6.61, part held 4.61, not advanced
ES due 3.61, part held, 4.61 not advanced.

Damage Repairs

The surveyor reports p.o. steam cylinder of windlass found fractured and temporary metalock repair effected. The surveyor now recommends port side steam cylinder of windlass be re-examined and dealt with ^{by} 3/62.

(4 months limit)

It is submitted that the vessel WILL BE eligible for the record MBS 4/61 (ES with date) when the survey has been completed. Subject as now recommended.

WEG
11/6

Lloyd's Register
Foundation