

COPY

# LLOYD'S REGISTER OF SHIPPING

BELONGS TO  
ROTTERDAM REPORT NO. 52130

Part of ROTTERDAM

16th August, 1961

This is to Certify that I have

part  
Surveyed the Machinery of the s.s. "SANROCCO", 7181 tons gross of  
Panama, whilst lying afloat and placed in drydock at this port on the  
26th July, 1961 and subsequent dates for Completion General Examination  
Adv.ES, Adv.MBS, Condition and Repairs . . . . .

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will **Recommend** that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
MBS 4-61 when completed as previously recommended, ES with date when the  
Survey has been completed . . . . .

and that her Machinery Classification Record be continued in the Book  
without the condition of class relating to the main sea suction valve  
chest.

To complete the MBS the safety valves of all boilers remain to be adjusted  
under steam.

Parts now examined: (C.S. Items only) for adv. ES:-

All sea connections.  
Main circulating pump.

*D. Kampman*

Engineer Surveyor to Lloyd's Register.  
D. Kampman.

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CS Continuous Survey of Engines  
DBS Donkey Boiler Survey  
ES Engine Special Survey  
MBS Main Boiler Survey  
MES Modified Survey of Oil Engines  
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey  
SPS Steampipe Survey  
TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

icate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
e the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
nderstood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held  
or any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
lication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
yors, or other Officers or Agents of the Society."

© 2021

Register  
Foundation

010605-010614-0219