

Columbean

F.E.



Phone Lombard 3543.

## Lloyd's Register of Shipping,

324 Bourse.

PHILADELPHIA, October 10th, 1913.

LOYD'S REGISTER  
LONDON  
20 OCT 1913  
RECEIVED

S/S "SANTA CLARA" Phil. report No. 2047.

S. Sir:

I am in receipt of the classing letter of September 30th relating to the spare gear on this vessel and in reply I have to state that two connecting rod bolts, two crank pin bolts and two main bearing bolts were supplied and placed on board, which I regret was not fully stated on the report.

I am, Sir,

Your obedient Servant,

The Secretary,  
London.



© 2021

Lloyd's Register  
Foundation

WEB-FRAMES, In Fore Body, No. and spacing				BULKHEADS.				In Vessel.		Per Rule.		Thickness.		Horizontal	
brdth. & thicknss												Inches.		Inches.	
No. of Side Stringers															
WEB FRAMES, In E. & B. Space, No. & spacing				W. T. BULKHEADS				7		7		as per approval			
				COLLISION				1		1		as per approval			



Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.

Referred to the Chief Engineer Surveyor.

*C. A. Hill*

Also for Mr. S. A. Hill to note.

ACT 20 1913

*S. A. Hill*



© 2021

Lloyd's Register  
Foundation