



Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 1st December, 1948.

RECEIVED

- 3 DEC 1948

Dear Sir,

Reference

"OTTO BANCK" Sld.F.E.Rpt.No.34989.

With reference to your classing letter of the 19th ultimo, we have to confirm the battery charging cables (19/.064) are V.C. and not V.I.R. as given in the report. The error is regretted.

With regard to the oil engine driving the 15 K.W. generator set, we are given to understand this was not built under survey. The electrical contractors, Messrs. Campbell & Isherwood, Newcastle, have been in touch with their Liverpool branch with a view to the Makers' test certificate for this motor being obtained. This will be forwarded as soon as possible.

Yours faithfully,

THE SURVEYORS,
PER:

The Secretary,
LONDON.




© 2021

Lloyd's Register
Foundation

010652-010661-0039

Referred to the D.O.



For Engineer Surveyors (F.E. Rpts.) to note.
Notes. A unit fuller upmation sh 3/12/48

RECEIVED
MAR 12 1948
MAR 12 1948



© 2021

Lloyd's Register
Foundation

D
rem
SSE
ated