

SHIP'S NAME

"BARBARA"

REPORT

11724.
Nap.

No. 5352

Standing Conditions of Class:

Subject to indented side shell plating in way
Nos. 4, 5, 8 & 9 cargo tanks (s.s.) being examined & dealt with as necessary next
Special Survey, and to leaky shell riveting in way of bilge keel (p.s.) being
dealt with as necessary next dry docking.

Endorsement of Class (B) (As before ~~or~~ None)

Nature of Present Survey: (Afloat and in dry dock) ✓

minimization of damage caused by heavy weather — some repairs effected.

Recommendation:

Submitted ship is eligible to assigned a record of docking 3, 55
subject as above, also to bottom plating in way of Nos. 6 and 7
tanks, after pump room and No. 8 tank (p.s.) being specially
examined and dealt with as necessary at next Special Survey.

3, 55 Ino. Subject.

Endorsement of class (B)

Indents in stem & side
shell plating, etc. (p.s.) ✓

apx
C.S.S. Records Dept.
to note. H.W. damage

© 2021



010675 - 010686 - 0080