

COPY OF AIR LETTER.

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, E.C.3

Reference: 'Class'
(S)

5th October, 1951.

Dear Sir,

I am in receipt of your air mail letters of the 12th and 21st ultimo, respecting the Steamer "ROCKSIDE", the contents of which have been noted.

In the circumstances, the Committee, who have recently had the case before them, have given instructions for the vessel's class to be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

With regard to the remarks contained in the last paragraph of your letter of the 21st ultimo, I have to say that there are no records in this Office of unsympathetic treatment in connection with the postponement of surveys and there are no reports of survey, either from Manila or Osaka, of screwshaft trouble in this ship.

I shall be glad if you will inform the Owners of the Committee's decision referred to above.

Yours faithfully,

Assistant Clerk to the
Classification CommitteeThe Principal Surveyor,
MONTREAL.

© 2021

Lloyd's Register
Foundation