

27 SEP 1951

"ROCKSIDE"

Withdrawal of Class

Enquiries have been made to ascertain the Owners' reasons for the withdrawal of class, but the reply is not informative.

There are no records of unsympathetic treatment in respect to postponement of Surveys and there are no reports of Survey either at Manila or Osaka of screwshaft trouble in this ship.

IT IS SUBMITTED that, as requested by the Owners, the class be withdrawn and three dots (...) inserted.

Bell

26.9.51.



Lloyd's Register
Foundation

010720-010726-0007