

10 JUN 1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FORT PERROT". REPORT Mch. No. 12176

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to indented sheerstrake plates Nos. 6 & 7 from aft, stringer plate etc. (s.s.) at the first convenient opportunity and to ( a bower anchor being supplied and two bower anchors and stream anchor on board being submitted to the Statutory Test).

ACTION HAS BEEN DEFERRED for repairs on account of "enemy action" damage.

The Manchester Surveyors report the vessel placed in dry dock and on account of "enemy action" damage, as above subsequent fire and grounding, renewals and/or repairs to shell and deck plating, framing, floors, beams, inner bottom plating, hatchways, indented plating, as above, and to minor items effected. The Surveyors recommended cargo battens in after holds and 'tween decks be refitted and the first opportunity.

It is submitted the vessel is eligible to remain as classed with record of survey 5.45, subject as recommended and as above except as regards indented plating (s.s.).

5.45 Mch, subject, without.



010720-010726-0035