

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen. London

Telephone: ROYal 3551 (6 Lines)

25th June, 1955.

assn.S.

Dear Sirs,

s.s. "BALTYK"

I have to inform you that a report of survey carried out at Buenos Aires early this month has come to hand from the Society's Surveyors from which it is noted that on examination of the starboard main boiler defective rivets were found on upper back plate seam, both circumferential seams and lower butt straps.

Temporary repairs have been effected, and the Surveyors stated that the Owners were making arrangements for permanent repairs to be dealt with at a home port. It is therefore recommended that the riveting of the starboard boiler should be examined, and I shall be glad if you will ascertain from the Owners, and let me know, at which port the Surveyors to this Society can make the necessary inspection.

Yours faithfully,

Clerk to the  
Classification Committee

Messrs. Gdynia America Shipping  
Lines (London) Ltd.,  
Coventry Court,  
47, Whitcomb Street,  
W.C.2.



© 2021

Lloyd's Register  
Foundation

010720-010726-0184