

Empire Thacheray

Nov. 100676

It is observed that a date is given to the fitting of sea connections & pumping arrangements by the above Surveyors, but they have omitted to fill in the blank page of their report in respect of pumps and pumping arrangements.

As there is no reference to this having been attended to by the Sld. Surveyors it is submitted the report be returned to the above Surveyors for completion.

Otherwise in order



© 2021

Lloyd's Register
Foundation

010727-010733-0163