


Telegrams :
Bruntons, Sudbury, Suffolk

Telephone :
Sudbury, Suffolk 2708

BRUNTONS (SUDBURY 1919) LIMITED

SUDBURY, SUFFOLK

MARINE ENGINEERS



Directors:
ROBERT STEELE (CHAIRMAN)
ALFRED LONG, A.C.I.S. (MANAGING)
GROUP CAPTAIN PAUL GARDNER THOMSON
FREDERICK GOLD

Secretary:
ALAN LONG

SPECIALISTS IN:
MARINE PROPELLORS
STERN GEAR AND
ALL UNDERWATER
FITTINGS

Our Ref: L/JMH.

3rd March, 1950.

Your Ref: S.

RECEIVED

- 4 MAR 1950

The Secretary,
Lloyd's Register of Shipping AND
71, Fenchurch Street,
London E.C.3.

Dear Sir,

Messrs. Crossley Brothers Con.No.20430
m.v. "MARBURY"

We thank you for your letter dated the 2nd March, 1950, and have pleasure in appending hereunder information in connection with the above mentioned order and trust that you will find this sufficient to enable you to dispose with this matter.

1. Crossley's letter ^{to us} 30.6.47. RF/GP mentioned that you had approved the torsional vibration characteristics of the shaft system for the sterngear to the above mentioned order.
2. Our letter to Crossley Bros Ltd., 4.7.47 stated that we assumed that these people had obtained your approval of the sterngear drawings and enclosed a final set of drawings as under.

Sterngear drawing No. 3/1858D
Propeller " " 6/2779
Stern tube lubrication " " 3/1975.

3. Details of our sublet orders are as follows:-
Our Order No. D 7239 11.7.47 Steven & Struthers Ltd.,
Propellers.
" " " D 7261 21.7.47 Fife Forge Co, Ltd.,
Shaft forgings.

Duplicate copies of these orders were sent to you on 11th and 21st July 1947 respectively.

010783-010790-0102½

over.....

Lloyd's Register of Shipping.

- 2 -

4. The Stern gear was despatched to Crossley Bros,
Openshaw on 26th August 1948.

Yours faithfully,
BRUNTONS (SUDBURY 1919) LIMITED.

Agueahong
MANAGING DIRECTOR.



© 2021

Lloyd's Register
Foundation

0102 1/2

Referred to the Chief Engineer Surveyor.

Referred to Mr. Peixoto

Handwritten initials

For Engineer Surveyors (F.E. Rpts.) to note.

RECEIVED DIRECTOR

RECEIVED (MILITARY) DIVISION

observed on Sept 1948. The instrument was checked to correct proc.

- 5 -

Original to refer to



© 2021

Lloyd's Register Foundation