

"MARBURY"

Before this case receives consideration,
IT IS SUBMITTED the Liverpool Surveyors be asked to state
the Moment of Inertia of the new propeller, since it is
observed there is a calculated critical not far above the
maximum running speed.

At the same time, they should be informed that
plans of sterntube and screwshaft do not appear to have
been submitted for approval, and their comments are desired.

They should also be referred to the "As fitted"
plan ~~and~~ of pumping arrangements, and be asked to state
whether the Rule requirements have been satisfied
in all respects.

26. 1. 50.



Edk

© 2021

Lloyd's Register
Foundation

010783-010790-0115