

# REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office)

Date of writing Report.....19..... When handed in at Local Office.....19..... Port of Sydney N.S.W.

No. in Survey held at Sydney N.S.W. Date. First Survey 26/3/42 Last Survey 26/3/42 19.....  
Reg. Book. (No. of Visits. 1)

82891 on the Machinery of the Steel T.S.S. "Strathallan"

Tonnage { Gross 23122 Vessel built at Barras By whom Vickers-Armstrongs, Ltd When 1938 3  
 Net 14134 Engines made at Barras By whom Vickers-Armstrongs, Ltd When 1938  
 Nominal Horse Power 4912 Boilers, when made (Main) 1938 (Aux. Donkey) 1938  
 No. of Main Boilers 4 Owners P.O. Jim New Co Owners' Address London  
 No. of Donkey Boilers 2 Managers ✓ (if not already recorded in Appendix to Register Book.)  
 Steam Pressure in Main Boilers ✓ Port London Voyage ✓  
 in Donkey Boilers ✓ If Surveyed Afloat or in Dry Dock (State name of Dock.)

Last Report No. Port

## Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Was a damage report made by anyone else? If so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

" " Donkey " " " "

If not, state for what reasons. What parts of the Boilers could not be thus thoroughly examined?

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

State latest date of internal examination of each boiler. Present condition of funnel(s)

Did the Surveyor examine the Safety Valves of the Main Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of the Donkey Boilers? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine the drain plugs of the Main Boilers? and of the Donkey Boilers?

Did the Surveyor examine all the mountings of the Main Boilers? and of the Donkey Boilers?

Has the screw shaft now been drawn and examined? Has it a continuous liner? Is an approved oil retaining appliance fitted at the after end?

Has shaft now been changed? If so, state reasons. Has the shaft now fitted been previously used? Has it a continuous liner?

Is an approved oil retaining appliance fitted at the after end? State date of examination of Screw Shaft. State the wear down in the stern bush. Is electric light and/or power fitted? If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses?

Has the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Engine parts, when referred to by numbers, should be counted from forward.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done

*(Empty space for notes)*

## General Observations, Opinion, and Recommendation:


(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11 \*LMC 9,11 or \*LMC 140 lb., PD, &c.) CS 3,34,

*(Empty space for observations)*

Survey Fee (per Section 29).....	£ : :	Fees applied for
Special Damage or Repair Fee (if any) (per Section 29.).....	£ : :	
Travelling expenses (if chargeable).....	£ : :	
		Received by me, £ : : 19

Committee's Minute Assigned As now 18th 4 DEC 1942

Engineer Surveyor to Lloyd's Register of Shipping.



Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to