

Rpt. 9B

REPORT OF MACHINERY SURVEYS AND REPAIRS

Received London

7 Jan 1963

Ship's Name ~~SS/MS~~ " CHOPIN" Gross tons 6987

Is there a rpt. 8? no Port Gdańsk Rpt. No. M 1143

No. of visits 1 First date & Last date 28-12-62

Interim Cert. issued & copy herewith? yes Damage rpt. issued & copy herewith? no Last rpt. (H.Q. only) ~~1585~~ 1585 Rjk

Date of completing rpt. 31-12-62 Surveyed at, if different from Port above Gdynia

Is a rpt. 9A attached? No. MN Nature of survey W & T

Survey fees Damage fee Expenses zł 80.-

£ 4. 0.0 & zł 210.-

less 10% = £ 3.10.0 & zł 190.-

S.A. fee -

DOCKING

Propeller Sea connections Oil gland

Fastenings Wear down of stern bush

Has screw/tube shaft been drawn? Date of examn.

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves { Sat adjusted to { Spt

Boiler securing arrangements

Main economisers Exhaust gas heated economisers

Steam heated steam generators Steam generator safety valves adjusted to

Forced circulating pumps Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of survey subject to distance piece for auxiliary boiler blowdown seavalve being further examined and dealt with as necessary at next drydocking and to all outstanding conditions of class being dealt with as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

FRIDAY 25 JAN 1963

Minute

Deferred for cp. ABS Subject.

Surveyor to Lloyd's Register of Shipping

G. Lee

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register Foundation

010797 - 010804 - 0021

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

Considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a Generators		l Generators & governors
b Exciters		
c Air coolers		m Motors
d Motors		n Switchboards & fittings
e Air coolers		o Circuit breakers
f Control gear cables, etc.		p Cables
g Insulation resistance		q Insulation resistance
h Insulating oil test		r Steering gear generators & motors
i Overspeed governors		s Navigation light indicators
j Magnetic couplings		
k Air gap		


PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Ship examined afloat & small fracture found in the welding connecting the distance piece for the Auxiliary Boiler blowdown seavalue to the ship's side.

As a temporary repair a cement box was fitted.

Survey confined to above.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register  
Foundation

