

15 MAR 1962

Received from Chief Ship Surveyor.....

SHIPS NAME "CHOPIN" REPORT Gdk. No. 891

GB

Outstanding Conditions of Class: SUBJECT to a bower anchor and 30 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix. (As before ~~xxxxxxx~~)

Nature of Present Survey: (Afloat ~~and on dry dock~~)

Equipment: supply of a bower anchor and 30 fathoms of chain cable as above: Spare bower anchor on board now reported to be damaged.

Recommendation:

SUBJECT to damaged spare bower anchor on board being renewed at the earliest opportunity but without other condition.

As Now. Subject Without.

IN S.R.L. APPENDIX. (Main structure partly of P.403 Steel)



© 2021

Handwritten signature and date 9-3-62.

Lloyd's Register Foundation

010797-010804-0048