

I have surveyed the above ship in accordance with the Rules for Damage Survey stated on 25th May 1963 at Abidjan due to a log fallen on deck across No.2 hatch and on the 2nd-4th July 1963 at Marseilles due to a log fallen on the Double bottom No.2 (stbd) tank top whilst handling loose cargo

EA

COPY

Ship's name

"LOBITO"

Port

GEN.

No.

28156

Last survey date

25.7.63.

Class is subject to

For conditions of class see previous endorsement.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Examination and repairs on account of damage sustained by cargo.

Recommendation

SUBJECT to deep tanks amidships not to be used in partially filled condition until suitable horizontal girders are fitted to side shell and bulkheads, also to No.2 D.B. tank top plating and internal structure (in way of temporary repairs effected Msl.7.63) being specially examined and dealt with as necessary by the Special Survey.

As now Subject amended.

IN S.R.L. APPENDIX  
Shell plates F.7 (s.s.f)  
and G.9 (p.s.f) indented.

End. S.1

Date of Committee

THURSDAY - 3 OCT 1963

Minute

As now Subject (hdm) 29

010835-010845-0123

© 2021

Lloyd's Register  
Foundation

POSTING

HEADER