

Received from Chief Ship Surveyor

10 OCT 1952

SHIP'S NAME 'S.N.A.6' REPORT Bhm. No. 480

Outstanding Conditions of Class: Subject to indented bottom shell plating in way of F.P. and No.1 D.B. tank being specially examined and dealt with as necessary by next Special Survey.

Endorsement of Class (B) (As before ~~er=None~~)

Nature of Present Survey: (Afloat and in dry dock) Docking.
Repairs to indented bottom plating, etc. as above, including Endorsement (B) items.
Alterations in accordance with approved plan.

Recommendation: SUBMITTED record of docking 7,52 be assigned, without special conditions.

7,52 Bhm Without.

DELETE 'ENDORSEMENT OF CLASS (B)'

✓ INSERT IN R.B.
"Cargo Battens Not Fitted"
"Tween deck tanks in mchy space"



© 2011
3-10-52.

010835-010845-0149

Lloyd's Register
Foundation