

REPORT of SURVEY for REPAIRS, &c.

Writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 69979 Survey held at on the Wood, Iron or Steel T.W. S. "Princess Joan" Date, First Survey 1930 Last Survey 19

TONNAGE—
GROSS 5251
UNDER DEK. 3163
NET 3023
Built at Glasgow By whom Fairfield Co. Ltd When 1930 MONTH 4
Owners Canadian Pacific Ry Co Owners' Address Victoria, B.C.
Managers _____ Port belonging to Victoria, B.C.

Surveyed Afloat or in Dry Dock? _____ Name of Dock _____ Destined Voyage _____
WB=CellDBorDBa _____ feet; uE&B _____ feet; f _____ feet }
total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ tons. }

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 3404 Port Ner

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined _____

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned or expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+ 100 A1 5-32		+ LMC
With freeboard		4.30
In Channel Sound		CL
service Seattle and Skagway.		
FITTED FOR OIL FUEL 4.30		
I.P. ABOVE 160° F.		

Society's Freeboard (if assigned) as painted on Ship and now verified } _____ ft. _____ ins.

Was a damage report made by anyone else? If so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR _____

DISCLOSED SECTION No. 697

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year.
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained. (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	length size (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	Rule length size
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute TUE. 4 APR 1933
Character Assigned Withdraw Class & insert
Surveyor to Lloyd's Register of Shipping. General Committee
Thursday, 6th April 1933
Lloyd's Register
Decision of Classing
Committee confirmed

Dear Capt. ... with reference ... that you ... I ... appreciate ... with you

Is Certificate required? If so, to be sent to