

nt to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Sta T.S. "PRINCESS JOAN" Report Elb No. 50330

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/12.)

ature of Survey 1st Entry When due _____ Revised Rules _____

✠ 100 A. I. (Steel). With Keelboard

For Channel + Sound Services - Seattle to Skagway

2 D^{ks} (Stl - Weather D^k pt ws), 3rd D^k (Stl) in holds.

Cell D.B. a. v E. B 126' + 81' 319t, D.T. + 32' 98t, D.T. a 38' 122t, F.P.T. 38t.

F.K, 6 B.H. (Coll B.H. to Weather D^k, 5 B.H. to 2nd D^k), pt cem, Lloyds A + CP.

B. F 307'.

Upper Bridge 208'.



© 2021

Lloyd's Register
Foundation

010846-010857-0033