

Messrs. Taikoo Dockyard & Engineering Co. of Hong Kong, Hong Kong.

500,4,61 Blk.

Sister Ship "KALILI"

Yard No. 486

Received by Chief Ship Surveyor  
GB

Received from Chief Ship Surveyor

SHIP'S NAME

m.s. "KURWINA"

REPORT H.Kg.

No. 16252

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

L. 92'-0"

B. 22'-0"

D. 10'-0"

This ship is reported to have been built under Special Survey in conformity with or by standards equivalent to the Society's Rules and Regulations and the Secretary's letters.

IT IS THEREFORE SUBMITTED the ship is eligible to be classed:-

100A "New Guinea Coasting Service"  
"DTf - Oil FP above 150 F"  
DS 5,61

WHEN a report has been received of its satisfactory condition on arrival within the service limits.

1 dk; EW  
Mchy Aft  
O.L. 99'-6"  
E.B: 22'-1"  
DBuE pt O.F. pt F.W; DTa 14t f 29t; FPT 16t.  
4BH, LACP.  
P 36'  
R.O.F: Nil  
"b"

The Surveyors at Sydney should be requested to generally examine the ship on arrival within its service limits and furnish a Rpt.8.

X 5/6

DA.

13.7.61.



© 2021

Lloyd's Register  
Foundation

010846 - 010857 - 0205

p223