


NN "HOLLYLEAF"  
 n.7. Hollybranch



F.E.

Received by Chief Ship Surveyor

16.5.17

Received from Chief Ship Surveyor

Rm

69865

VESSEL'S NAME

Shells. Helium

Rpt.

Still

No. 29868.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 33.5

Depth "d" 9.25

Framing: Table No. 3. page 9.

Description

Single angle as approved

Longitudinal No. 4522.

Proportions

$$\frac{\text{Length}}{\text{Depth}} = 12.85$$

Deck Sheerstrake as approved.

The vessel has been examined in dry dock,  
 the bottom cleaned & scraped & the survey completed


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✕ 100 A.1. (Shell) as recommended.

✕ 100 A.1. (Shell)

1 DK. (Shell) 1000 DK

F.P.T. 386.

FK. 3BH. Can. Lloyd's approved. @ 50' B.G. Fz. 1 inch abt.



© 2021

Lloyd's Register  
 Foundation

010890-010904-0039