

"STANVALE".

Got.

23115.

*Uddevalle
Got 4/5/57.*

Before this case receives consideration the Got. Surveyors should be asked to forward the report on the oil fired donkey boilers (Nos. 7467/68). At the same time they should be advised that Mdb. Rpt. 20824 on two boilers (Nos 7511/12) built by the same firm, Stockton Chemical Engineers and Riley Boilers Ltd., states that the boilers are for Uddevallavarvet Yard No 160. As boilers Nos. 7467/68, have been fitted to Yard no. 160 the Got. Surveyors should state for which ship boilers 7511/12 are intended. In this connection, it is thought that the Got. Surveyors should be sent a copy of the letter dated 30.4.57 to the Birmingham Surveyors regarding the numbering of the stamp mark on the exhaust gas economiser fitted on Yard No. 160.

The Got. Surveyors should be asked if one 4" direct bilge suction has been fitted at the port forward end of the engine room as shown on the plan and omitted from the Report. *Yes*


No machinery Certificates appear to have been received and these should be forwarded. ✓

R

checked JB.

18.4.57.

43014



© 2020

Lloyd's Register
Foundation

010913-010923-0027