



Lloyd's Register of Shipping.

25, Victoria Road,

Dartmouth, 13.7.1942.

S.S. "MARI II"

Dartmouth Report No. 7503.

Reference

S.

Dear Sir,

In reply to the enquiries contained in your Classing Letters of 23rd ult. and 10th inst. I have to state that the bracket floor reverse frames and vertical struts are as indicated on the midship section.

The Thickness of Bridge and Forecastle Deck Plating is 5/16" and 1/4" respectively and Wood Sheathing 2.3/4" Thick Fitted on the Forecastle Deck only. Further I have to confirm that the Diameter of the I.P. Cylinder is 28.1/8", but that the Registered Depth should be 17.4. as appearing in the Register Book.

I am, Dear Sir,

Yours faithfully,

Ats. R. J. H.

The Secretary,

WOKINGHAM.



© 2021

010982-010991-0015

Lloyd's Register
Foundation

Noted
1.c.8
10.4.42

H
RBF

GA

4 JUL 1942

ME



© 2021

Lloyd's Register
Foundation

Noted
1.c.8
10.4.42