

"MARI II"

to

The equipment on board this vessel is reported is in order as regards size, weight and test except as regards the 3 bower anchors and the stream anchor.

The collective weight of the bower anchors is slightly deficient (lwt. 3qrs. 7lbs. or 2%) and as these anchors are not new it is submitted these might be accepted.

The stream anchor is in order as regards weight.

There is no information, however, as to the origin and test of the four anchors, but as the vessel was classed with the Bureau Veritas it might be assumed that they have been satisfactorily tested by the Surveyors to that Society.

It is a matter for consideration whether the anchors might be accepted on this assumption [or, alternatively, required to be tested at the end of the present emergency.]

#  
*Ship Equip.*

*accepted by  
Committee*

*23/6/42*



© 2021  
*Handwritten initials*

22.6.42

Lloyd's Register  
Foundation  
010982-010991-0017