


MARI II

Ply Rpt. No 7503

The First Entry Report now received from the Surveyor has been examined, and on being compared with the plans it is observed that there are a number of discrepancies. These have been indicated in pencil on the report, and it is submitted the report and plans be returned to the Surveyor for amendment as necessary.

The reference "Length of the poop joined to bridge 90ft." as indicated under the heading "Particulars for record in the Register Book" is not understood, as, according to the freeboard report and the plans, there is no poop.

It is concluded that the particulars of water ballast are as shown on the capacity plan.



J.C.D.
19.5.42

A handwritten signature in dark ink, appearing to be 'J.C.D.', located to the right of the typed name and date.

LR Ply 6/5/42

Lloyd's Register
Foundation

010982-010991-0026