

9 NOV 1931

s. s. "CHESTERFIELD".

London 96841a.

The screwshaft survey became due in 8,31.

In reply to enquiry the Montreal Surveyor encloses a letter from the Owners stating that it is not desired to continue the vessel's class with this Society.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...



9.11.31.



© 2021

Lloyd's Register  
Foundation

010992-011000-0225