

## MARKS FOR IDENTIFICATION ON ENGINE PARTS M.V."ALDEGONDA"

S.B.

Airpump shaft	Lloyd's	F.S.	23.4.30	347
Crankshaft front part	"	M.K.	10.6.30	3518
Crankshaft back part	"	M.K.	10.6.30	3519
Flywheelshaft	"	M.K.	10.6.30	3520
Thrustshaft	"	F.N.B.	3.9.30	145
Intermediate shaft	"	H.P.B.	25.7.30	702

Piston rods

Lloyd's	805	F.N.B.	11.6.30
"	804	"	"
"	803	"	"
"	802	"	"
"	801	"	"
"	800	"	"

Connecting Rods

Lloyd's	853	F.N.B.	11.6.30
"	852	"	"
"	851	"	"
"	850	"	"
"	849	"	"
"	848	"	"

Cylinders

Lloyd's	713	H.P.B.	4.8.30
"	696	"	25.7.30
"	693	"	23.7.30
"	714	"	4.8.30
"	697	"	25.7.30
"	692	"	25.7.30

H.P. Airpump liner

Lloyd's 82 F.N.B. 26.8.30.

L.P. Airpump liner

Lloyd's 54 F.N.B. 21.8.30

6 Crossheads

each marked: Lloyd's 3955 H.K. 6.3.30

Coolers

H.P.	Lloyd's	198	F.N.B.	18.9.30
I.P.	"	202	"	"
L.P.	"	206	"	"

Coolerchest

Lloyd's 248 F.N.B. 2.10.30.



© 2021

Lloyd's Register  
Foundation

011011-011023-0337 1/6



## MARKS FOR IDENTIFICATION ON ENGINE PARTS M.V. "ALDEGONDA"

S.B.

Airpump shaft	Lloyd's	F.S.	23.4.30	347
Crankshaft front part	"	M.K.	10.6.30	3518
Crankshaft back part	"	M.K.	10.6.30	3519
Flywheelshaft	"	M.K.	10.6.30	3520
Thrustshaft	"	F.N.B.	3.9.30	145
Intermediate shaft	"	H.P.B.	25.7.30	702

Piston rods

Lloyd's	805	F.N.B.	11.6.30
"	804	"	"
"	803	"	"
"	802	"	"
"	801	"	"
"	800	"	"

Connecting Rods

Lloyd's	853	F.N.B.	11.6.30
"	852	"	"
"	851	"	"
"	850	"	"
"	849	"	"
"	848	"	"

Cylinders

Lloyd's	713	H.P.B.	4.8.30
"	696	"	25.7.30
"	693	"	23.7.30
"	714	"	4.8.30
"	697	"	25.7.30
"	692	"	25.7.30

H.P. Airpump liner

Lloyd's 82 F.N.B. 26.8.30.

L.P. Airpump liner

Lloyd's 54 F.N.B. 21.8.30

6 Crossheads

each marked: Lloyd's 3955 H.K. 6.3.30

Coolers

H.P.	Lloyd's	198	F.N.B.	18.9.30
I.P.	"	202	"	"
L.P.	"	206	"	"

Coolerchest

Lloyd's 248 F.N.B. 2.10.30.



© 2021

Lloyd's Register  
Foundation

0337 1/4



P.S.

Airpump shaft	Lloyd's	I.L.	7547	11.4.30
Crankshaft front part	"	M.B.	8963	19.5.30
Crankshaft back "	"	M.B.	8962	19.5.30
Flywheel shaft	"	M.B.	8961	19.5.30
Thrustshaft	"	F.N.B.	144	3.9.30
Intermediate shaft	"	H.P.B.	703	25.7.30.

Piston rods

Lloyd's	811	F.N.B.	11.6.30
"	810	"	"
"	809	"	"
"	808	"	"
"	807	"	"
"	806	"	"

Connecting Rods

Lloyd's	859	F.N.B.	11.6.30
"	858	"	"
"	857	"	"
"	856	"	"
"	855	"	"
"	854	"	"

Cylinders

Lloyd's	53	F.N.B.	21.8.30
"	52	"	"
"	51	"	"
"	50	"	"
"	49	"	"
"	48	"	"

H.P. Airpump liner

Lloyd's 81 F.N.B. 26.8.30

L.P. Airpump liner

Lloyd's 715 H.P.B. 4.8.30

6 Crossheads

each marked: Lloyd's 3955 H.K. 6.3.30 878

Coolers

H.P.	Lloyd's	F.N.B.	18.9.30	197
I.P.	"	"	"	201
L.P.	"	"	"	2045

Coolerchest

Lloyd's 249 F.N.B. 2.10.30

Inblast air receivers

Lloyd's	442	M.K.	1.7.30
"	1027	F.K.	23.7.30

Starting air receivers

Lloyd's	739	F.N.B.	27.5.30
"	740	"	"

DONKEY BOILER

Lloyd's 368 F.N.B. 21-8-30.

© 2021

Lloyd's Register  
Foundation

0337 1/4



Airpump shaft	Lloyd's	I.L.	7547	11.4.30
Crankshaft front part	"	M.B.	8963	19.5.30
Crankshaft back "	"	M.B.	8962	19.5.30
Flywheel shaft	"	M.B.	8961	19.5.30
Thrustshaft	"	F.N.B.	144	3.9.30
Intermediate shaft	"	H.P.B.	703	25.7.30.

Piston rods

Lloyd's	811	F.N.B.	11.6.30
"	810	"	"
"	809	"	"
"	808	"	"
"	807	"	"
"	806	"	"

Connecting Rods

Lloyd's	859	F.N.B.	11.6.30
"	858	"	"
"	857	"	"
"	856	"	"
"	855	"	"
"	854	"	"

Cylinders

Lloyd's	53	F.N.B.	21.8.30
"	52	"	"
"	51	"	"
"	50	"	"
"	49	"	"
"	48	"	"

H.P. Airpump liner

Lloyd's	81	F.N.B.	26.8.30
---------	----	--------	---------

L.P. Airpump liner

Lloyd's	715	H.P.B.	4.8.30
---------	-----	--------	--------

6 Crossheads

each marked: Lloyd's 3955 H.K. 6.3.30 878

Coolers

H.P.	Lloyd's	F.N.B.	18.9.30	197
I.P.	"	"	"	201
L.P.	"	"	"	2045

Coolerchest

Lloyd's	249	F.N.B.	2.10.30
---------	-----	--------	---------

Inblast air receivers

Lloyd's	442	M.K.	1.7.30
"	1027	F.K.	23.7.30

Starting air receivers

Lloyd's	739	F.N.B.	27.5.30
"	740	"	"

DONKEY BOILER

Lloyd's	368	F.N.B.	21.8.30.
---------	-----	--------	----------

© 2021

Lloyd's Register  
Foundation



SPARE PARTS

1 Cylinder	Lloyd's	250	F.N.B.	21.10.30
1 "	"	251	"	"
1 H.P. Cooler	"	252	"	"
1 I.P. "	"	254	"	"
1 L.P. "	"	353	"	"
1 H.P. airpump liner	"	308	"	15.10.30
1 L.P. "	"	304	"	"
1 crankshafthalf	"	999	N.S.	6.10.30.

-0-0-0-0-0-0-

*L. W. Beumer*



© 2021

Lloyd's Register  
Foundation

0337 5/4



SPARE PARTS

1 Cylinder	Lloyd's	250	F.N.B.	21.10.30
1 "	"	251	"	"
1 H.P. Cooler	"	252	"	"
1 I.P. "	"	254	"	"
1 L.P. "	"	353	"	"
1 H.P. airpump liner	"	308	"	15.10.30
1 L.P. " "	"	304	"	"
1 crankshaft half	"	999	N.S.	6.10.30.

-o-o-o-o-o-o-o-

*P. W. Bennett*

