

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19 MAY 1930 Port of ...

No. in Reg. Book 31066 on the Wood, Iron or Steel Linn Co. 'PERCH ROCK' Survey held at Birkenhead Date, First Survey 4 Last Survey 15/5/1930

TONNAGE: GROSS 466, UNDER DK 766, NET 285. Built at Dundee By whom Calidon S B & E Co Ltd When 1929 4

Owners The Mayor, Aldermen & Burgesses of the Borough of Wallasey Managers ... Port belonging to Liverpool

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Birkenhead Destined Voyage ... Particulars of Classification

WB=CellDBorDBa feet; uE&B feet; f feet total capacity tons. FPT tons; APT tons; MT feet tons.

Last Report, No. 96140 Port Liv. Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking Vessel placed in dry dock, bottom and rudder, cleaned examined and coated

SUMMARY OF DAMAGE REPAIRS: Shell Plates, Frames, R. Frames, Floors, Beams, Str. Plates, Dk. Plates, Other Items

PRESENT CONDITION OF THE Decks, Caulking of Decks, Coamings, Beams & Fastenings, Outside Plating, Breasthooks, Transoms, Frames, Reverse Frames, Longitudinals, Transverses, Floors, Keelsons, Stringers, Inner Bottom Plating

General Observations, Opinion as to Class, Recommendation, &c.: This vessel as now seen is in a good condition and in my opinion is eligible to remain as classed with fresh record of survey Bkn 5-30.

Survey Fee (per Section 20), Special Damage or Repair Fee (if any), Travelling Expenses (if chargeable), Second Surveyor's Fee (if any)

Signature of Surveyor to Lloyd's Register of Shipping

Committee's Minute 23 MAY 1930 Character Assigned 100 A1 - S. 30. Bkn. With fld for ferry service

