

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "HRVATSKA"

Rpt.

Spt. No. 1026

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/42)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel, being in occupied territory, the class was omitted from the 1944 copy of the Register Book.

A complete LMC and screw shaft survey has now been carried out.

A boiler, ex. "KARADJORDJE" now fitted, examined and repairs effected.

Minor repairs effected to main engines.

Auxiliary machinery and electrical equipment repaired.

IT IS SUBMITTED that this vessel is eligible for the Record LMC 10.46, (180 lb.)
S 10.46, (OG).

Insert in R.B.

☞ NB 13 refitted 46.

1 SB, 3 cf, GS 56, Hs 2324 FD.

MN 147.

9.5
23. 11. 46.



© 2021

Lloyd's Register
Foundation

011047-011056-0151