

5 NOV 1954

Received from Chief Ship Surveyor

SHIP NAME "CERION" REPORT Sng. No. 10409

Standing Conditions of Class:

Subject to set up and indented bottom shell plates (p & s) in way of No.3 D.B. tank being specially examined and dealt with as necessary at the next drydocking.

Assessment of Class (B) (~~As before~~ or None)

Place of Present Survey: (Afloat and in dry dock)

Docking: Damage repairs (causes unknown).

Recommendation:

SUBMITTED record of docking 9,54 be assigned, subject as above, and to shell plate B.4 (p.s.f.) being dealt with by next Special Survey.

9,54 Sng. Subject.



© 2021

Lloyd's Register  
Foundation

01057-011061-0065