



4E

23 OCT 1961

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME "DOM JOSE" (ex. SAN PAULO) REPORT RIO No. 8075..

The class of this vessel was expunged from the Register Book in 1.60 for non-compliance with the Rules, and the Surveyor now reports a Special Survey for re-classification now carried out.

The Engine Survey, Boiler Survey, Tailshaft Survey and Steam Pipe Survey now carried out in accordance with the Rules and the machinery stated to be in good condition.

IT IS SUBMITTED that this vessel's machinery is eligible to be re-classified in the Register Book with fresh records of: ^{PLC} ES 6.61, MBS 6.61 (W.T.), TS (OG) (p & s) 6.61 and SPS 6.61.

JH

19.10.61.

Yes

NOTE.

It is concluded that the forced draught fans were examined.



© 2021

Lloyd's Register Foundation

Vertical text on the left margin: 05, MES, MBS, ES, DRS, CS, ABS, Certificate is issued, While the Contract, be understood to, able for any insur, a publication of, 2007, or 01, 150m, 2007.