

8m. 2.24

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S. S. "BULAN" Report Gls No. 43741

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

1st Entry

When due

This vessel has been built in accordance with the Revised Rules and the owner's consent thereto has been obtained. (see letter)

✦ 100A.1. (Steel) with freeboard.

2 SKs (weather SK deck, 2nd SK steel, w.s.).

Cell D.B. 176' 248t, F.P.T 14t, A.P.T. 27t.

F.K., 5B.H. (Coll BH to weather SK), ft cm, Lloyds A. CP.



© 2021

20-6-24

Lloyd's Register Foundation

(Corresponding Draught 13 ft. 3 ins.

Freeboards compared and found correct by _____ Date _____