

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME Steel Screw "BABINDA" Report Gls. No. 56871

**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due --

\*100A1

1 Dk.

Cell. DB 114' 186t, FPTs 44t, APT 26t.

FK, 3 BH, pt. cem. Lloyd's A &amp; CP

Q 103', B 11', F 35'

Machy. aft.

*Note:- Extreme Breadth over Belting 31'-7"*

It is concluded the scantlings of the margin plate are as approved, but the Surveyors should be requested to state if this is so.