

Received from Chief Ship Surveyor..... 13 FEB 1962

SHIP'S NAME "ARDROSS"

REPORT NAG.

No. 1137

EA

Outstanding Conditions of Class:

and at oxtter (E.W. and reinforced 2,60) being specially examined next drydocking.

SUBJECT to sternframe at solepiece

See blue mt.  
of. 28/2/62

R.L. Appendix. (As before or ~~None~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking:-

Permanent repairs to stevedore damage.

Wear and tear repairs.

Deferred repairs to wasted keel plating.

Recommendation:


SUBMITTED record of DS 11,61 be assigned, subject as above and to corroded keel plating except No.2 being specially examined and dealt with as necessary next drydocking.

DS 11,61 Subject.

IN S.R.L. APPENDIX.

Keel plates Nos. 3 & 4 from aft indented.

IT IS FURTHER SUBMITTED the Surveyors be informed that the ship was subject to "sternframe at solepiece and at oxtter (E.W. and reinforced 2,60) being specially examined next drydocking", and they be requested to advise whether this has now been done but inadvertently omitted from the Report.



© 2021

Lloyd's Register  
Foundation

011227-011234-0331