

2m.11.35.

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

S.S. "BROOMFIELD"

Report

Liv.

No. 110700

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

FIRST ENTRY

When due

100A1

1 Dk.


Cell.DB 86' 113t, FPT 110t, APT 47t.

FK, 3BH, Cem., LLOYD'S A &amp; CP.

Q 102', F 25'.


Machy. aft

O.L. 176' -9".


  
5.5.38



This is generally a sister ship to the "BRACKENFIELD".



Lloyd's Register  
Foundation

011251-011258-0034

Intercostal Plate...

Spacing.....