

29 JUL 1954

NAME "MARIA POMPEI" REPORT Sld. No. 36284

## Standing Conditions of Class:

Subject to indented shell plating,  
etc. (p & s.f.) and bridge sheerstrake plate No.1 from aft etc.  
(p.s.) being dealt with by next Special Survey.

ACTION is DEFERRED for drydocking (contact with buoy).

Assessment of Class (B) (~~As before~~ or None)

Days due: SPECIAL SURVEY (C) due 6,54.

Place of Present Survey: (~~At sea~~ and in dry dock)

Docking.

## Special Features:

Interim Certificate in order (Yes-No-None)

Ins Outstanding: (~~If any~~ for S.S. or A.S.)

All Special Survey requirements.

to be completed by:

## Recommendation:

SUBMITTED record of docking 7,54 be assigned,  
subject as above, but further ACTION be DEFERRED  
for Special Survey.

7,54 Sld. Subject.

DELETE FROM S.R.L.  
Drydocking (contact with buoy).



© 2021

Lloyd's Register  
Foundation



(Cert. B.) 20m, 9.48. (MADE