

LONDON COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

SUNDERLAND RPT. NO. 36284



Port SUNDERLAND.

9th July, 1954.

This is to Certify that I have

Surveyed the S.S. "CRACKSHOT", 2379 Tons, of Newcastle-on-Tyne whilst lying in dry dock at Sunderland on the 6th July, 1954.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be the condition of the

hull plating, rudder, sternframe and propeller is such that no repairs are considered necessary until such time as the special survey (due 6.54) is required to be carried out.

being fit to carry The tail shaft was examined in 3.54 and found satisfactory. The wear down has now been checked and is not excessive.

G. Buchanan

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, and be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member or the Surveyors, or other Officers or Agents of the Society."