

20 AUG 1963

Ship's Name SS/~~MS~~ "TRIS IERARCHE" Gross tons 1366
Is there a rpt. 9? Yes. Port Piraeus Rpt. No. 10440
No. of visits 2 First date 1-8-63 Last date 2-8-63
Interim Cert. issued & copy herewith? Yes. Damage rpt. issued & copy herewith? No. Last rpt. (H.Q. only) PIR 10111
Date of completing rpt. 3-8-63 Surveyed at, if different from Port above
Surveyed afloat and/or in D.D. Both. Last date of examination in D.D. 2-8-63
Has a Load Line Survey been held? No. Freeboard Marks verified

State which additional Rpt. 8 is attached: (~~XXXX~~PS); (~~XXXX~~XXXX)

Survey fees Damage fee Expenses £ 0. 8. 0
DS £ 15. 0. 0 Wue

S.A. fee

I have surveyed the above ship in accordance with the Rules for Docking and completion of General Examination for postponement of Special Survey,

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Condition of Class.

Indented shell plates E5, F6, 7, G6, 7, (ssa), E4, 5, F4, 5, G4, 5 (ssf), E4, 5, 6 G5, 6 (psf), A8, B7 (psa), A2 (ssf), A3, 4 (p&sf), B5 (psf) and set in shell plates D5, E7, F9, G9 (ssf) and indented shell plating in way of poop accommodation (p&s) all examined this time and still remain efficient, no repairs were effected.

However it is recommended that the above shell plates be re-examined and dealt with as necessary at the Special Survey.

General Examination of vessel in drydock carried out and all found satisfactory, it is therefore submitted that the Owner's request for postponement of Special Survey until 1, 64 may merit the favourable consideration of the Committee.

S.R.L. Appendix.

Indented shell plate A7 (ps from aft) examined and still remains efficient.

I recommend that this ship remain as classed with ~~without~~ fresh record of dry docking survey 8, 63, subject to indented shell plates E5, F6, 7, G6, 7 (ssa), E4, 5, F4, 5, G4, 5 (ssf), E4, 5, 6, G5, 6 (psf), A8, B7 (psa), A2 (ssf), A3, 4 (p&sf), B5 (psf) and set in ~~in~~ shell plates D5, E7, F9, G9 (ssf) and indented shell plating in way of poop accommodation (p&s) being re-examined and dealt with as necessary at the Special Survey.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

FRIDAY - 4 OCT 1963

Minute

White PIR
(pp)

#

Deferred for SS.
SS. 8.63 Subject
MBS. 8.63 SPS. 8.63(Postponement of SS
until 1.64 approved)

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT.

Lloyd's Register
Foundation

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

Ship's Name SS/~~MS~~ "TRIS IERARCHE"

S.S. () Due

Port Piraeus

Rpt. No. 10440

<u>Examined & condition</u>		<u>Examined & condition</u>	
In dry dock from	1-8-63	* Air & sounding pipes	Above deck-Good.
" " " to	2-8-63	Doublers under " "	N.E.
Shell plating	Good.	Steering arrangements (main)	Good.
Sternframe	Good.	" " (aux)	Good.
Rudder	Good.	Windlass	Good.
Was rudder lifted?	No.	Masts & rigging	Good. From deck.
Plating, etc. in way of shell openings	Good.	Hand pumps & suction	N.E.
Side scuttles & deadlights	N.E.	W.T. doors	N.E.
Overbd. scuppers & discharges	N.E.	Bulwarks, freeing ports, etc.	Good.
F.P. spaces	N.E.	Summer freeboard as verified	-
Chain locker	N.E.		
A.P. spaces	N.E.		
Engine space	N.E.		
Boiler space	N.E.	<u>EQUIPMENT:</u>	
Under E. & B.	N.E.	Equipment letter	o
Coal bunker	None.	Fee ltr., if diff. from eqpt. ltr.	
Tunnel & well	N.E.	Anchors: No. on board	
Cement, asphalt, etc., on btm. shell	N.E.	Cables {	State if ranged Not ranged.
Weather decks	Good.		Length on board
* Casings	Good.		Mean dias. range from to
* Deckhouses	Good.		Rule length Dia.
* Superstructures	Good.	Mooring ropes	Good.
* Skylights	Good.		
* Companionways	Good.		
* Hatchways	Good.		
* Ventilators	Good.		
Other items:			

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2021

Surveyor to Lloyd's Register of Shipping

Foundation

011378-011385-0187 2/2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
"	'Tween decks				
No. 3	Hold		O.F. bunkers		
"	'Tween decks				
			Settling tanks		
No. 4	Hold	N.E		N.T.	
"	'Tween decks		Deep tanks		
No. 5	Hold				
"	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
"	'Tween decks		Other tanks:		
	Cargo battens				
	Ceiling, etc.				



© 2021

Lloyd's Register
Foundation