

is subject to

20 MAR 1962

.....
by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... "RODOPI"..... REPORT..... Ant..... No. 37480.....

ES due 3.61 - now held.

MBS due 4.62 - now held.

Screwshaft examined.

Damage - cause not stated.

Main crankshaft lifted, bearings remetalled and shaft re-aligned.

IT IS SUBMITTED that this vessel is eligible for the record ES 2.62, MBS 2.62 and TS (CL) 1.62.



© 2021

16.3.62

Lloyd's Register Foundation