

LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3

Calle Gran Vía, 83, 1.º izqda.

Apartado de Correos N.º 286, Bilbao

Telegramas: Register, Bilbao , 17th June, 1961

Teléfono 16995

Ref: Classn (S)

RECEIVED

20 JUN 1961

Dear Sir,

Ans'd.....

"Rushwood"

In reply to your classing letter of 13th June, 1961, we have to confirm that three bower anchors are now on board the above ship. The starboard bower anchor and 15 fathoms of chain cable were stated to have been fitted in Philadelphia and it was assumed that they had been reported by the Surveyors there. The particulars for this anchor are as follow:-

B.C. 16882, 19-12-60, 117820 LR. 7350

The foreccastle fashion plate (s.s.) was examined at this time and found to be without defects. It is assumed that this has been previously repaired and it is submitted that this condition of class may now be deleted.

Yours faithfully,

George S. McIntosh.

For the Surveyors.

Secretary

on.



© 2021

Lloyd's Register
Foundation

011478-011484-0228

SR.

REPORTS

See blue endorsement
dated 21/6/61. *GO* 21/6/61.

• STOVETUE ENT TOY

• VILCINTIST ETUOY

ENT (.S.S.) STAL NOISEST EITSESTOT ENT
STONTHW ED OF ENUCT BNE ENT ENT JA BENTREX
NEED ENT ENT ENT ENT ENT ENT ENT ENT
ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
• ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT

0637 .SI 036711 .03-31-61 .38391 .C.E

STEL TO JETTEL GULESALO THOY OF VIFET NI
ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
• ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
TO ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
• ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT
• ENT ENT ENT ENT ENT ENT ENT ENT ENT ENT

• ENT ENT ENT

• ENT ENT

1961 . ENT ENT



© 2021

Lloyd's Register
Foundation