

13th June, 1961.

LBAO.

065 " RUSHWOOD" - ~~As~~ recommended.

I have to inform you that prior to your survey the class is subject to the bower anchor, and 15 fathoms of chain cable being supplied at the earliest opportunity; also to forecandle shion plate etc. (s.s.) being specially examined and dealt with as necessary at the next dry docking, in addition to the items mentioned in your report.

Please confirm that three bower anchors are now on board, reported, in which case the condition of class regarding this item can be amended accordingly.



© 2021

Lloyd's Register  
Foundation

011478-011484-0229