

Received from Chief Surveyors

"STAR"

REPORT

Bal. No. 11051.

the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

are to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been shown the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case. The Classing Committee may have all the salient points presented in the endorsement."—(*Extract from Sub-Committee's Report, 24/5/92.*)

NO. ^(C) SPECIAL SURVEY/PARTLY HELD.

Docking. Damage repairs.

3.57.

When proposed to be completed.

E S. S. :-

See this report.

N O T E D

FORSEMENT OF CERTIFICATE.

11 plates G.5 & 6 and 'H'
ake in way(p.s.) from aft indented.
G.5 (s.s.f.) indented.

Bal. 2,57" on completion.

portion of the Survey held includes the requirements of a General Examination.

It is concluded the structure under the engines and boilers could be included in the list of items to complete the S.S. the Surveyors' confirmation is desired.

The Surveyors should be requested to furnish a copy of approved plan of the rudder fitted at this time.

C.S.S. Records Dept.

to note.

RECEIVED
U.S.S.
RECORDS
DEPT.

011485-011492-0135