

-6 MAY #3

Ship's Name ~~SS/MS~~ "CLEARWAY" Gross tons 276

Is there a rpt. 9? YES Port BARROW Rpt. No. 4146

No. of visits 3 First date 9.4.63 Last date 29.4.63

Interim Cert. issued & copy herewith? YES Damage rpt. issued & copy herewith? NO Last rpt. (H.Q. only) 4079 Ban

Date of completing rpt. 1.5.63 Surveyed at, if different from Port above WHITEHAVEN

Surveyed afloat and/or in D.D. Afloat & on Grid on Grid

Has a Load Line Survey been held? YES Annual Last date of examination in D.D. 9.4.63

Freeboard Marks verified YES

State which additional Rpt. 8 is attached: (~~CRK~~); (PS); (~~DRS~~); (~~YES~~); (~~REG~~)

Survey fees £3.0.0d Damage fee - Expenses £6.4.3d

S.A. fee

9 MAY 1963

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

I have surveyed the above ship in accordance with the Rules for Annual Docking

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

Now Done:

Bottom and Rudder cleaned, examined and recoated. The Engine & Boiler Room Spaces examined generally.

Wear & Tear Repairs:

Rudder Bottom Pintle renewed.

Per Special Reasons List.

The indented bilge plating etc (Port side) now specially examined and found to remain efficient.

An Annual Freeboard Survey has been carried out at this time. (Report forwarded).

I recommend that this ship remain as classed with ~~without~~ fresh record of dry docking 4-63, subject to the indented plating etc (port side) being specially examined at the next drydocking.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee WEDNESDAY 12 JUN 1963

Minute J.S. 4.63 Subject MBS. 4.63 SPS. 4.63

(J.H. Smith) Supervisor to Lloyd's Register of Shipping

ALSO FOR
SPL FOR
TRO
SRL ✓
POSTING
HEADER
CERT



011493-011498-014542

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/~~MS~~ "CLEARWAY"

S.S. () Due

Port BARROW

Rpt. No. 4146

		<u>Examined & condition</u>		<u>Examined & condition</u>
Under deck			* Air & sounding pipes	Above Deck GOOD
On grid iron	9.4.63	GOOD	Doublers under	N.E.
" " " to			Steering arrangements (main)	GOOD
Shell plating	Efficient		" " (aux)	
Sternframe	GOOD		Windlass	GOOD
Rudder	GOOD		Masts & rigging	From Deck GOOD
Was rudder lifted?	YES		Hand pumps & suction	N.E.
Deck structure			Welding	
of steel spaces			Bulwarks, freeing ports, etc.	GOOD
Side scuttles				
Lighting			Summer freeboard as verified	1 - 5 1/2"
Overbd. scuppers & discharges	GOOD			
F.P. spaces	N.E.			
Chain locker	N.E.			
A.P. spaces	N.E.			
Engine space	GOOD			
Boiler space	GOOD		<u>EQUIPMENT:</u>	
Under E. & B.	N.E.		Equipment letter	d
Coal bunker	Outside	GOOD	Fee ltr., if diff. from eqpt. ltr.	-
Tunnel & well	NONE		Anchors: No. on board	2
Cement, asphalt, etc., on btm. shell	N.E.		State if ranged	NO
Weather decks	GOOD		Length on board	N.E.
* Casings	GOOD		Cables {	Mean dias. range from
* Deckhouses	GOOD			Rule length
* Superstructure			Mooring ropes	GOOD
* Skylights	GOOD			
* Companionways	GOOD			
* Hatchways	GOOD			
* Ventilators	GOOD			
Other items:				

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

© 2021

 J.H. Smith
 Surveyor to Lloyd's Register of Shipping
 Lloyd's Register Foundation
 011493-011498 0145 2

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold		F.P. tank		
„	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold				
„	'Tween decks				
No. 3	Hold		O.F. bunkers		
„	'Tween decks				
			Settling tanks		
No. 4	Hold				
„	'Tween decks				
			Deep tanks		
No. 5	Hold				
„	'Tween decks		Side tanks		
No. 6	Hold		Wing tanks		
„	'Tween decks				
			Other tanks:		
	Cargo battens				
	Ceiling, etc.				



© 2021

Lloyd's Register
Foundation