

-6. MAY 63

Ship's Name SS/MX "CLEARWAY"

Gross tons 276

Is there a rpt. 8? YES

Port BARROW

Rpt. No. 4146

No. of visits 3

First date 9.4.63

Last date 29.4.63

Interim Cert. issued & copy herewith? YES

Damage rpt. issued & copy herewith? NO

Last rpt. (H.Q. only)

Date of completing rpt. 1.5.63

Surveyed at, if different from Port above WHITEHAVEN

Is a rpt. 9A attached? NO

MN (46)

Nature of survey Main Boiler survey  
Steam Pipe survey

Survey fees £9.0.0d

Damage fee -

Expenses £4.4.6d.

S.A. fee -

DOCKING

Propeller GOOD

Sea connections N.E.

Oil gland GOOD

Fastenings GOOD

Wear down of stern bush Close fit

Has screw/tube shaft been drawn? NO

Date of examn. -

Has shaft been changed? -

Has shaft now fitted been previously used? -

Has shaft now examined/fitted a continuous liner? -

Approved oil gland? -

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG)

MAIN

19.4.63 GOOD

Air heaters -

Superheaters -

Safety valves GOOD

Mountings, doors and fastenings GOOD

Safety valves adjusted to { Sat 180 lb. GOOD  
Spt -

Boiler securing arrangements GOOD

Main economisers Exhaust gas heated economisers -

Steam heated steam generators Steam generator safety valves adjusted to -

Forced circulating pumps Funnel GOOD

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules? -

Were oil burning system & remote controls examined in accordance with rules? -

I recommend that the machinery of this ship remain as classed with ~~without~~ fresh record of

M.B.S. 4-63 and Sps. 4-63.

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)


Surveyor to Lloyd's Register of Shipping

Date of Committee WEDNESDAY 12 JUN 1963

Minute

As now  
MBS. 4.63  
SPS. 4.63.

011443-011498-0149



© 2021

Lloyd's Register

Foundation

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark thus should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN Tested 360 lb. Copper GOOD  
 AUXILIARY None  
 (over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested? -

Were selected copper pipes annealed? YES

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a	Generators	l Generators & governors
b	Exciters	
c	Air coolers	m Motors
d	Motors	
e	Air coolers	n Switchboards & fittings
f	Control gear cables, etc.	o Circuit breakers
g	Insulation resistance	p Cables
h	Insulating oil test	q Insulation resistance
i	Overspeed governors	r Steering gear generators & motors
j	Magnetic couplings	s Navigation light indicators
k	Air gap	

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.

