

POSTPONED SURVEYS.

Tw. Sc. S.S. "TETI"

No. 79155 in R.B.

Tonnage

Owners

Port of Registry

Repairs to indented and wavy shell plating etc. and

indented keel and bottom plating etc. by 10.52.
75 fathoms of worn chain cable to be renewed and 15 fms.

Supplied as soon as possible (by 10.52, Pir. 7.52'
withheld for repairs and equipment).

Both propellers to be renewed and both screwshafts examined
by 10.52.

be held

Action has been deferred in the past on account of the vessel
laid up.

The Piraeus Surveyors now state that there are no changes
circumstances of this case.

Surveyors' recommendations

Permanent repairs will
be made at the Special Survey
before assignment of a
notation could have been

14
2
53

© 2021

Lloyd's Register
Foundation