

"ARABIA"

Gls. 72061  
Sld. 34810  
Liv. 126437

IT IS SUBMITTED that this vessel's  
Refrigerating Installation is eligible for the Record  
LLOYD'S RMC 1.48.

Subject to defective brine lead  
to No. 3 lower 'tween deck starboard after battery in  
No. 3 cooler cross alleyway being renewed and insulation  
in way being refitted before loading refrigerated cargo,  
and to defective "Malone" thermometer to forward end of  
No. 2 upper 'tween deck starboard after chamber being  
renewed on vessel's return to the U.K.

The Liverpool Surveyors should be  
informed that in the Secretary's letter "E" of 9. 11. 45.  
to the Glasgow Surveyors it was stated that the insta-  
llation would be eligible for the notation LLOYD'S RMC  
No. 2 lower 'tween decks for temp. - 5° F, all other  
chambers for temp. 15° F.

It is observed from the cooling  
down test that no differentiation has been made in this *indications*  
respect between the various chambers, also no ~~restriction~~  
as to temperature has been recommended against the vessel's  
class.

They should, therefore, be requested  
to raise the question with the Owners as to whether they  
still desire to adhere to the specification in this respect.

If such should be the case it would  
be necessary for another cooling down test to be carried  
out.



17. 1. 48.  
© 2021

Lloyd's Register  
Foundation

011603-011609-0121

*See Div. reply 5/2/48*