

Lloyd's Register of Shipping.

Ship's Name *HOLLY BANK* "EMPIRE SOUTHEY" *h.l. OCEAN UNIT* Official No. 169023

Memorandum of alterations reported since ship was surveyed for assignment of Load Lines in

ALTERATIONS: NEW GUNNERS' ACCOMMODATION FITTED IN AFTER TWEEN DECK

SANITARY DISCHARGE: from gunners' accommodation in after 'tween
1 W.C discharge led overboard below freeboard deck from 2
Baltic type water closets incorporating an automatic non-
return valve and an automatic non return valve fitted at
ship's side.
Washbasin and sink discharges led overboard below freeboard
deck fitted with 2 automatic non return valves (1 discharge
Port side and 1 Starboard side).

SIDE SCUTTLES: 7, 10" dia. side scuttles fitted through ship's side below
freeboard deck in new accommodation of strong construction
and each fitted with efficient deadlights.

VENTILATORS: 2, 9" and 4, 6" additional cowl ventilators fitted on
weather deck in way of new accommodation, coamings 36" high x
.32 thick closed by means of wood plugs and canvas covers.

A copy of the above will be supplied to Owners for placing on board the vessel.

Alexander P. Moore.
Glasgow.
18th October, 1943.

(Wokingham)

M

