

"TIO PEPE"

IT IS SUBMITTED the Cadiz Surveyors be informed that it will be necessary for a complete Machinery Survey to be held including an examination of the screwshaft, also it will be necessary to verify whether a 2" branch bilge suction has been fitted in the Engine Room in addition to the two direct suctions of 2½" diameter and also to verify whether the various oil fuel valves have been made controllable in accordance with Rule requirements.

*[Signature]*  
29.10.53.

*Nr. 12* *[Signature]* *(H)*  
*lc*



© 2021

Lloyd's Register  
Foundation

011610-011618-0147