

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

18th October, 1962

C.  
H/MRN

Dear Sir,

M.S. "SOUTHERN ENTERPRISE"

Before your Report No. 2132 receives the consideration of the Committee I shall be glad if you will state your reasons for recommending that the class should be subject to the main engine lubricating oil pump drive gears being re-newed by July 1963. In future similar cases when a condition of class is recommended your reasons for making such a recommendation should be clearly stated in the body of your report.

Yours faithfully,

pro Clerk to the  
Classification Committee

The Surveyor,  
MOMBASA.



© 2021

011646-011656-0283

Lloyd's Register  
Foundation