


COPY

LLOYD'S REGISTER OF SHIPPING



Port of Mombasa,

29th September, 1962.

This is to Certify *that I have surveyed part of the machinery of the m.v. "SOUTHERN ENTERPRISE", 239 Gross tons of Port for Victoria, Seychelles, for Continuous Survey, whilst lying afloat and on the slipway at Mombasa on the 24th September, 1962 and subsequently.*

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned

CS, with date, on completion of survey, subject to the main engine lubricating oil pump drive gears being renewed by July, 1963.

Parts now examined:—

Main engine No.1, 2, 3 & 4 cylinders, pistons, covers, rods, valves and gear, gudgeon and bottom end bearings and crankpins.

Main engine No.4 & 5 main bearings and crankshaft journals.

Main engine turbocharger.

Main engine driven salt water, bilge, and lubricating oil pumps.

Both main and the auxiliary air receiver.

Pallast and General Service pump.

P. Betteridge/

P. Betteridge
Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CSM Continuous Survey of Machinery
DBS Donkey Boiler Survey
ES Engine Special Survey

MBS Main Boiler Survey
OF Fitted for oil fuel (date) FP above 150°F.
SGS Steam Generator Survey
SPS Steampipe Survey

TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2021

Lloyd's Register
Foundation
011646-011656-0289